



**IMG\_0090**.....400356 mE 6484121 mN  
Concrete slab, toilet block with asbestos roofing (very fragmented); Asbestos fencing as well with D. Cooper.



**IMG\_0091**.....400364 mE 6484099 mN  
Long buried terracotta pipe.



**IMG\_0092**.....400358 mE 6484100 mN  
Corrugated iron water tank within Agave spp.bushes.



**IMG\_0093**.....400365 mE 6484108 mN  
Broken asbestos fence. Looking southwest.



**IMG\_0094**.....400379 mE 6484124 mN  
Fence line; Flame tree with Darren Cooper



**IMG\_0095**.....400374 mE 6484122 mN  
D. Cooper near fenceline.





**IMG\_0096**.....400352 mE 6484140 mN  
Limestone aggregate driveway with brick rubble pile.



**IMG\_0097**.....400352 mE 6484140 mN  
Close view of clay brick rubble



**IMG\_0098**.....400361 mE 6484132 mN  
Three pieces of patterned earthenware



**IMG\_0099**.....400377 mE 6484137 mN  
Concrete foundation measuring 3 m x 4 m with Darren Cooper. Note asbestos sheeting.



**IMG\_0105**.....400387 mE 6484197 mN  
Toilet block/ washhouse with Asbestos roofing, down pipe breather for septic with D. Cooper



**IMG\_0106**.....400387 mE 6484197 mN  
Toilet block/ washhouse with Asbestos roofing, down pipe breather for septic with D. Cooper





**IMG\_0107**.....400387 mE 6484197 mN  
Toilet block/ washhouse with Asbestos roofing, down pipe breather for septic with D. Cooper



**IMG\_0108**.....400387 mE 6484197 mN  
Toilet block/ washhouse with Asbestos roofing, down pipe breather for septic with D. Cooper



**IMG\_0109**.....400387 mE 6484197 mN  
Steel bolt/stud for fixing wooden wall bearers.



**IMG\_0110**.....400387 mE 6484197 mN  
Toilet block/ washhouse with Asbestos roofing, down pipe breather for septic with Darren Cooper.



**IMG\_0111**.....400387 mE 6484214 mN  
Cast Iron Stove Top



**IMG\_0112**.....400387 mE 6484223 mN  
D. Cooper near concrete leach drain.





**IMG\_0114**.....400397 mE 6484222 mN  
Concrete Floor 3m x 5m next to open septic tanks with gal-  
vanised iron sheets on top



**IMG\_0115**.....400409 mE 6484250 mN  
44 gallon drum - not insitu. With D. Cooper



**IMG\_0116**.....400399 mE 6484253 mN  
Concrete floor/toilet slab. Wooden floor joists bolted to floor.  
Note terracotta pipe.



**IMG\_0117**.....400399 mE 6484253 mN  
Close view of wooden floor bearers bolted to concrete floor.



**IMG\_0118**.....400399 mE 6484253 mN  
Close view of wooden joist with trenching for wooden verti-  
cal studs.



**IMG\_0119**.....400399 mE 6484253 mN  
Bunnings' handscrawled on sheets.





**IMG\_0120**.....400391 mE 6484254 mN  
Water pipe outlet with galvanised star picket. With Darren Cooper.



**IMG\_0121**.....400391 mE 6484254 mN  
Asbestos-lined pipe.



**IMG\_0122**.....400390 mE 6484265 mN  
Big shady corkwood tree with Darren Cooper.



**IMG\_0123**.....400390 mE 6484265 mN  
Close view of horizontal cut made into corkwood tree.



**IMG\_0124**.....400392 mE 6484284 mN  
Tree with wire wrapped around the trunk; Agave spp. also present



**IMG\_0125**.....400392 mE 6484284 mN  
Tree with wire wrapped around the trunk; Agave spp. also present





**IMG\_0126**.....400389 mE 6484284 mN  
Telstra service hole with Darren Cooper.



**IMG\_0128**.....400408 mE 6484273 mN  
Fallen corrugated iron fence; Agave plants



**IMG\_0129**.....400416 mE 6484271 mN  
Fallen fence post



**IMG\_0134**.....400374 mE 6484309 mN  
Children's toy "Hot Wheels Car"



**IMG\_0135**.....400374 mE 6484309 mN  
Children's toy "Hot Wheels Car"




**IMG\_0136**.....400374 mE 6484309 mN  
Children's toy "Hot Wheels Car"





**IMG\_0137**.....400398 mE 6484323 mN  
Crushed steel can.



**IMG\_0138**.....400398 mE 6484323 mN  
Ceramic Egg-cup



**IMG\_0139**.....400398 mE 6484323 mN  
Ceramic Egg-cup



**IMG\_0140**.....400398 mE 6484323 mN  
Broken ceramic fragment and glassware.



**IMG\_0141**.....400398 mE 6484323 mN  
Patterned ceramic plate fragment



**IMG\_0142**.....400398 mE 6484323 mN  
Concrete floor 8 m x 3m . Asbestos sheets and two septic tanks.





**IMG\_0143**.....400393 mE 6484356 mN  
House water drain (terracotta) and cast iron drain cover



**IMG\_0144**.....400393 mE 6484356 mN  
House water drain (terracotta) with galvanised steel pipe.




**IMG\_0145**.....400382 mE 6484347 mN  
Collected items including pipe fragments, ant caps, ceramics, bottle tops, broken darts, broken toys etc.



**IMG\_0146**.....400382 mE 6484347 mN  
Collected items including pipe fragments, ant caps, ceramics, bottle tops, broken darts, broken toys etc.



**IMG\_0147**.....400382 mE 6484347 mN  
Collected items including pipe fragments, ant caps, ceramics, bottle tops, broken darts, broken toys etc.



**IMG\_0148**.....400382 mE 6484347 mN  
Broken WhizzWheels jeep base, produced between 1971 and 1973.





**IMG\_0149**.....400382 mE 6484347 mN  
Close view of Cottee's Coola bottle cap



**IMG\_0150**.....400382 mE 6484347 mN  
Close view of Coca Cola bottle cap



**IMG\_0151**.....400382 mE 6484347 mN  
Broken plastic toy sniper



**IMG\_0152**.....400378 mE 6484409 mN  
A concrete plinth from 1982 with two handmarks marking the period. With Darren Cooper.



**IMG\_0153**.....400378 mE 6484409 mN  
A concrete plinth from 1982 with two handmarks marking the period.



**IMG\_0154**.....400378 mE 6484409 mN  
The left hand side of the plinth, showing a handprint and '19'.





**IMG\_0155**.....400378 mE 6484409 mN  
The right hand side of the plinth, showing a hand and foot print and '82'.



**IMG\_0159**.....400401 mE 6484425 mN  
Concrete pad/ septic with Darren Cooper.



**IMG\_0160**.....400410 mE 6484430 mN  
Agave spp. Patch



**IMG\_0161**.....400148 mE 6484487 mN  
Dump of asbestos, wire, miniorb roll of tin; old fencing wire;  
Located on graded area & old track leading NE off main rack



**IMG\_0162**.....400148 mE 6484487 mN  
Close view of old-style chicken wire.



**IMG\_0163**.....400148 mE 6484487 mN  
Concrete floor with steel mesh





**IMG\_0164**.....400148 mE 6484487 mN  
View east along old track



**IMG\_0165**.....400148 mE 6484487 mN  
View east along old track with Darren Cooper near old dump



**IMG\_0166**.....400244 mE 6484123 mN  
Existing view of tennis court with Darren Cooper looking north.



**IMG\_0167**.....400244 mE 6484123 mN  
Light purple glassware



**IMG\_0169**.....400263 mE 6484021 mN  
Concrete foundation or wall



**IMG\_0170**.....400351 mE 6483998 mN  
Small wooden structure: wooden base and skirts with floors of jarrah timber sleepers.





**IMG\_0171**.....400351 mE 6483998 mN  
Small wooden structure: wooden base and skirts with floors of jarrah timber sleepers. Close view



**IMG\_0172**.....400333 mE 6484038 mN  
Concrete flooring with wooden rough-hewn timbers and large galvanised bolts. Asbestos corrugated sheets



**IMG\_0173**.....400333 mE 6484038 mN  
Concrete flooring with wooden rough-hewn timbers and large galvanised bolts. Asbestos corrugated sheets



**IMG\_0174**.....400333 mE 6484038 mN  
View of large galvanised bullet head bolts.



**IMG\_0175**.....400338 mE 6484058 mN  
Modern rubbish dump.



**IMG\_0176**.....400341 mE 6484080 mN  
Modern water tank





**IMG\_0177**.....400356 mE 6484076 mN  
Modern water tank



**IMG\_0178**.....400356 mE 6484076 mN  
Modern water tank (internal)



**IMG\_0179**.....400352 mE 6484095 mN  
Close view of large steel bolts within concrete foundations.



**IMG\_0180**.....400352 mE 6484095 mN  
8 (4 x2) concrete 'feet' to support two water towers - one wooden beam at western end (may be be remanant of tower; Water tank found at Wpt 184). Lots of Agave spp. Plants



**IMG\_0181**.....400352 mE 6484095 mN  
8 (4 x2) concrete 'feet' to support two water towers - one wooden beam at western end (may be be remanant of tower; Water tank found at Wpt 184). Lots of Agave spp. Plants



**IMG\_0182**.....400332 mE 6484117 mN  
Avenue of trees to north





**IMG\_0183**.....400332 mE 6484117 mN  
Avenue of trees to north



**IMG\_0184**.....400415 mE 6483960 mN  
Brick plinth or footing wih non-insitu brickwork