



Rip & Respread Publication Report KIM0001

We're working for Western Australia.

Contents

1	PURPOSE	3
	SCOPE	
	SITE MAP	
	SITE PHOTOS	
	APPENDICES	
	Appendix 1: Species list	. 8
	Appendix 2: Additional Information	

Document Control

Owner	Regional Manager – Kimberley Region
Custodian	Regional Environmental Officer – Kimberley Region
Document Number	D20#1063442
Issue Date	December 2020

Amendments

Revision Number	Revision Date	Description of Key Changes	Section / Page No.
0	December 2020	Document Release	
1			

1 PURPOSE

This Rip & Respread Publication Report provides additional information on KIM0001.

2 SCOPE

The Revegetation was undertaken in 2014 to rehabilitate the Derby Highway Material Investigation Area. 3ha of topsoil was ripped and respreads

Table 1: Main Roads Landscaping / Revegetation Details

Main Roads Region	Kimberley Region
Road Name	Derby Highway
Road Number	H047
Local Government	Shire of Derby-West Kimberley
Start SLK	36.8
End SLK	36.8
Central GPS Coordinates	• Latitude (N): -17.33712608
	• Longitude (E): 123.663732
Custom Revegetation Reference	KIM0001
Number (RNN)	
Type of Method Undertaken	Rip & Respread
Area of Method Undertaken	3
Year(s) Method Occurred	2014
Brief description	Ripping and Respreading of the topsoil at the
	Derby Highway Material Investigation area to
	rehabilitate the areas that temporary clearing
	occurred.

3 SITE MAP



Figure 1: Revegetation Location

Document No: D20#1063442 Page 4 of 8

4 SITE PHOTOS



Figure 2: Revegetation Site 2016



Figure 3: Revegetation Site 2017

Document No: D20#1063442 Page 5 of 8



Figure 4: Revegetation Site 2020

5 APPENDICES

Appendix	Title
Appendix 1	N/A
Appendix 2	N/A

Appendix 1: Species list

N/A

Appendix 2: Additional Information

N/A